

Patent

Attorney Docket No.: 2207/13919




IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

APPLICANTS : Michael D. HAINES
SERIAL NO. : 10/024,724
FILED : Dec 21, 2001
PATENT NO. : 7,030,482 B2
ISSUED : April 18, 2006
FOR : METHOD AND APPARATUS FOR PROTECTING A DIE
FROM ESD EVENTS

Certificate
JUL 07 2006
of Correction

M/S: CERTIFICATE OF
CORRECTION BRANCH
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Certificate of Mailing	
I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: M/S: CERTIFICATE OF CORRECTION BRANCH, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450 on	
Date: <u>June 27, 2006</u>	Signature  Pilar Rodriguez

REQUEST FOR CERTIFICATE OF CORRECTION

Dear Sir:

We have compared the above patent with the application as filed and have found errors in the printing of the patent. We respectfully request that the enclosed Certificate of Correction on Form PTO-1050 be issued correcting the mistakes set forth therein under authority of 35 U.S.C. §254. The exact column and line number where the errors occurred in the patent are listed on the enclosed certificate.

The errors that appear in the patent are typographical errors made by the Patent Office and therefore, no fee is required.

The Office is hereby authorized to charge any additional fees, or credit any overpayments, to Deposit Account No. **11-0600**.

Respectfully submitted,

KENYON & KENYON

Dated: June 27, 2006

By: 
Sumit Bhattacharya
(Reg. No. 51,469)

KENYON & KENYON
333 West San Carlos St., Suite 600
San Jose, CA 95110

Telephone: (408) 975-7500
Facsimile: (408) 975-7501

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

PATENT NO : 7,030,482 B2

DATED : April 18, 2006

INVENTOR(S) : Michael D. Haines

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 6, line 2: "gasket is bonded, to" should be --gasket is bonded to--

Column 6, line 8: "of rater than" should be --of greater than--

MAILING ADDRESS OF SENDER: Attorney Ref.: 2207/10611
KENYON & KENYON LLP
333 W. San Carlos, Ste 600
San Jose, CA 95110
Telephone: (408) 975-7500

PATENT NO. 7,030,482 B2

Date: June , 2006

No. of additional copies

→

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

JUL 07 2006